


CINCH Product List:

- CINCH Regular Gopher Trap
- CINCH Extra Large Gopher Trap
- CINCH Cascade Gopher Trap
- CINCH Mole Trap

Additional set wires are available from your local dealer in packs of 10.




For A Dealer Near You Call
Mole Control Hotline
1-800-841-5676

CINCH Trap Company
PO Box 130
Hubbard, Oregon 97032

Dealer Name


HOW TO SET A CINCH MOLE TRAP

Step 1. Hold the trap so the set wires #A and #B are hanging loose. Pull the trigger wire #C back. The trap is now ready to set.



- A-Forward Set Wire
- B-Rear Set Wire
- C-Trigger Wire
- D-Active Jaw Wire


Step 2. Holding the trap firm with one hand, raise the active jaw wire #D and lower it to the opposite side of the trap base. Position the forward set wire across the active jaw wire as shown.



Step 3. Position the rear set wire #B across set wire #A. Push the trigger wire #C forward, making sure the set wire #B is positioned behind the tab as illustrated. When you push the trigger wire #C you are in the guide area on the rear of the trap base.



Step 4. The trap is now set and ready to be positioned into the mole run.



Mole Control



CINCH

Mole Traps

The Trap Professionals Use!

