


HOW TO SET TRAP



1. Depress Spring Bar Into Trap
2. Place Latch Bar Across the Spring Bar
3. Place Latch Bar in Trigger Wire

HOW TO PLACE TRAP

1. Find a fresh mound and dig to open tunnel.
2. Place Trap flush to tunnel opening.
3. Pack loose dirt around the base of trap.
Be sure and leave the light hole open - so the light and air will bring the gopher back.

FOR A SURE SET

1. Set the Latch Bar to the end of Trigger Wire
2. All burrs and sharp edges should be removed from the end of Latch Bar and Trigger Wire.
3. **"BE SURE AND KEEP FINGERS OUT OF SPRING BAR AREA WHILE SETTING!"**