

CINCH Product List

Regular Gopher Trap

Wide Jaw Gopher Trap

Cascade Gopher Trap

Mole Trap


Additional Set Wires Are Available
From Your Local Dealer In Packs of 10



For A Dealer Near You Call...

**GOPHER CONTROL
HOTLINE
1-800-841-5676**

CINCH Trap Company
PO Box 130, Hubbard, OR 97032



STEP 1: HOLD THE TRAP SO THE SET WIRES #A & #B ARE HANGING LOOSE. PULL THE TRIGGER WIRE #C BACK AS SHOWN IN THE ILLUSTRATION, THE TRAP IS NOW READY TO BE SET.

STEP 2: HOLDING THE TRAP FIRM WITH ONE HAND, RAISE THE ACTIVE JAW WIRE #D AND LOWER IT TO THE OPPOSITE SIDE OF THE TRAP BASE. POSITION THE FORWARD SET WIRE ACROSS THE ACTIVE JAW WIRE AS SHOWN.

STEP 3: POSITION THE REAR SET WIRE #B ACROSS SET WIRE #A. PUSH THE TRIGGER WIRE #C FORWARD, MAKING SURE THE SET WIRE #B IS POSITIONED BEHIND THE TAB AS ILLUSTRATED. WHEN YOU PUSH THE TRIGGER WIRE #C MAKE SURE YOU ARE IN THE GUIDE AREA ON THE REAR OF THE TRAP BASE.



STEP 4: THE TRAP IS NOW SET AND READY TO BE POSITIONED INTO THE GOPHER RUN.

HOW TO SET A CINCH TRAP

CINCH
SURE
CATCH

**GOPHER
CONTROL**

BE SURE...IT'S A CINCH



* Made in The USA
* Tested & Approved By The U.S. Forest Service
* Over 100 Years Of Experience